







FAR LEFT 1969 Mark 1 2.5 Pl (oversteering) shows off Triumph's original Michelotti front LEFT 'Pl' stands for Petrol Injection; Aussieassembled 2.5 Pls featured metallic paint, vinylcovered C-pillars, trick wheels (or covers)



11 // Acceleration from manual cars isn't startling and carb-fed autos can be turgid. Our feature car had its auto replaced by a manual/overdrive

the Triumph employed an independent

with power-assisted front discs. A heater/

demister was standard, as were reclining

and very comfortable front bucket seats.

AMI attempted to boost the Triumph's

prestige credentials by building around 100

of its own 2000MD model. These came

Stromberg carburettors and overdrive, and

are now very scarce. Carbodies in the UK

produced an estate (station wagon) version

Chasing cheap performance for its TR5

sports car led Standard-Triumph to fatefully

adopt Lucas fuel-injection. Using a detuned

version of the TR5 engine, the 2.5 PI sedan

but these weren't sold new in Australia.

initially with wire-spoke wheels, triple

(AMI), alongside Toyotas and Ramblers, with a colour palette shared between AMI's various brands.

Local content including labour, trim, paint and tyres gave the Triumph a price advantage over the fully-imported Rover and put it into direct competition with Holden's EH Premier. Although down on power, the 2000 excelled in comfort and sophistication. Where the EH had rear 'cart' springs and dreadful drum brakes,

BELOW Triumph dropped troublesome Lucas fuel injection in 1975. Today, most engines have had their original Lucas parts replaced to make them both powerful and reliable



launched here in 1969 and was lauded rear-end and Macpherson struts at the front for its 170km/h performance. But it was derided shortly after for appalling reliability.

The PI introduced metallic paint to the Australian Triumph range, accompanied by vinyl-covered C-pillars and Rostyle wheel covers. In May 1970, the Mark 2 version was introduced featuring an elongated nose that echoed the new Triumph Stag, rectangular taillights and new bumpers.

Initially the range comprised 2000 and 2.5 PI models, but in March 1973, a 2500TC (twin-carburettor) model was added. In addition to the bigger engine, minus the tribulations of the cantankerous Lucas fuel injection, the TC sported improved seats and optional power steering. Power was boosted to 75kW and even automatic versions could reach 160km/h, thanks to revised gearing.

Triumph gave up on the fuel injected PI in mid-'75 and by 1976, only the 2500TC remained. But a flagship Triumph was revived in June '77 - the 2500S. Its engine was shifted marginally sideways to provide clearance for larger SU carburettors and a new exhaust manifold, but with power boosted by just 5kW, the effort seemed hardly worthwhile.

Under the 2500S nose was the first anti-roll bar fitted to these cars, combined with bigger tyres on Triumph Stag-style 14-inch rims. Power steering became standard with the 2500S, and air-con and even a sunroof were optional. All models were discontinued by the close of 1978.

On The Road

Having owned two and driven most 2000 and 2500 Triumph variants, my



commentary might struggle a bit in the area of objectivity. However, these truly are good cars and very underrated.

The first thing you notice is all-'round visibility and the quarter vents which survived all the way to the final 2500S - compensating for pretty ordinary ventilation. Vinyl seat trim used in early versions will become 'ouchy' after a few hours parked in summer sun, so shorts-wearers might prefer '70s models with cloth trim.

Low-geared steering combined with a massive steering wheel can make early cars feel cumbersome, but stylish aftermarket wheels remain available and transform the driver's relationship with the car.

My 1969 model was enhanced by wider wheels with 185/70 radials, upgraded dampers and some suspension tweaking by the celebrated Allan J. Heasman. At a time when Australia was converting to metric (though my speedo and brain hadn't), it was easy to forget that advisory signs were now showing km/h rather than mph.

The Triumph didn't care either and confidently scuttled through bends 60 percent faster than was recommended.

Ride quality, providing you don't go too extreme with the suspension fiddles, is brilliant. The downside of long-travel springs is body roll which manifests more ABOVE The 2000 was lauded for great all-'round visibility when launched - sunroof on this 2500 Injection Mark 2 magnifies that - and smaller aftermarket wheel sharpens the steering; headlight grilles good for country roads; stylish 14-inch mags pinched from Stag sports car

obviously in early cars than the later ones with their wider rear track. Keeping the back-end under tighter rein had the effect of reducing oversteer but also

made Mark 2 versions less responsive to throttle and steering inputs.

Don't be scared of taking your Triumph for a gallop through the unsealed countryside either. Unlike most models of their age, these cars lap up the rough stuff and handle corrugations with the same disdain as similarly-suspended Datsuns. In 1970, two Mark 2 PIs distinguished themselves by finishing second and fourth in the incredibly tough World Cup Rally. Acceleration, even from manual cars, isn't startling and carb-fed automatics can be downright turgid. Not surprisingly, the

owner of our featured PI Mark 2 elected to have its original auto transmission replaced (at some expense) by a manual/overdrive. Four-speed fuel economy can better

10L/100km but an auto used primarily in city traffic is likely to consume around 13. The fuel tank holds a generous 64 litres.



I Own One...

ACQUIRING THIS RARE, late-series PI was an opportunity that Graeme Oxley couldn't ignore. But it came at a cost. "I saw the car in 1996 at a British Display Day and discovered it was going to be sold as part of a divorce settlement," Graeme explained. "However, I couldn't buy it unless I sold my 2500S so it was a nervous wait."

Graeme's car is one of the last Graeme's car is one of the last PIs built in Australia and comes with the plastic grille that would be used on the replacement 2500S. It was assembled by AMI in December 1974 and sold through a dealer in Orange, NSW, before spending part of its life in Western Australia.

"The car has now done 613,000 kilometres, more than half of that distance while I've owned it, but you'd never know," he said.

The engine was rebuilt at 300,000 with a TR6 cam and manifold and the transmission converted from automatic to manual/overdrive. A new diff and Datsun half-shafts have also been installed and some work has been done to make the fuel-injection reliable.

"The original pump used to get so hot you couldn't touch it and on long trips I would cover it with a bag of ice to combat the heat," Graeme said. "Now it's got a Bosch pump and Volvo filter with the fuel lines positioned away from the exhaust and it works perfectly!" - CC

106

Triumph 2000/2500

Buyer's Checklist

Body & Chassis

Solid construction with a minimum of rust traps helped Triumphs survive for longer than many British designs, but time and neglect both take their toll. Check wheelarches for filler, bubbling around the windscreen rubbers, then look at the sills for bubbles or shonky repairs. More serious problems affect top suspension strut mounts and attachment points for the rear axle assembly. Make sure that the front-hinged bonnet closes squarely and the boot seal isn't allowing water into the luggage area. Early bumpers in good condition aren't easily found so watch for dents and peeling chrome. Other parts including light units, lenses, badges and bumpers for Mark 2s are still available new.

Engine & Transmission

Triumph engines are simple, durable and cheap to fix if they do eventually wear out. Exhaust smoke at start-up can signify valve stem leaks but a sustained blue haze means worn piston rings or liner damage. Top-end rattles can result from blocked oil ways leading to rocker shaft wear. Look and listen for exhaust manifold leaks and cracks. Check that the viscous-coupled fan on later cars still displays resistance when spun by hand. The fuel-injection system on surviving PI cars should by now have been upgraded using components not supplied by Lucas. Overdrive cars aren't common in Australia but make sure that the engine speed drops when O/D is engaged.

Suspension & Brakes Advanced for its time, the Triumph

Advanced for its time, the Triumph suspension is tough and pretty simple to maintain. The only major weakness was sliding-joint half-shafts which seize. These can be modified by Triumph specialists to take more durable Datsun shafts. Listen for clicks and clunks from the rear when accelerating or cornering. Worn steering rack bushes send road shock through the column and the lower joint can wear, leading to excessive play at the rim.

Interior & Electrics

Tired seat trim will need to be replaced second-hand or by a trimmer, but brand new carpet sets, sunvisors and door seals are available. Dash veneer splits with age and one supplier in the UK was asking \$700 for a kit of replacement timber items. Replacing the early generator with an alternator is advisable and make sure that the column stalks on Mark 2 cars haven't been broken and crudely repaired.



The most frustrating aspect of buying a 2000/2500 will be **prising one from its owner**

ABOVE Fully equipped in this instance means not only a fold-back sunroof but also rear venetian, bootlid luggage rack, mudflaps, tow bar and front nudge bar!

Overheating and blown head gaskets were a problem with early models. Neglected servicing can hurt crankshaft bearings so listen for rumbling when the engine is cold and kettle noises from the radiator when it's hot.

Buying

The most frustrating aspect of acquiring a 2000/2500 will be prising an excellent car from the grasp of its doting owner. Really good examples rarely make their way into the classifieds and you either need to keep an eye out at British vehicle display days or join a club.

"Most of the very good cars are owned by club members and that's where to go if you want one," PI Mark 2 owner Graeme Oxley advises.

"You want a car with good history that's sound in the body and has a decent interior. Virtually everything mechanical can still be bought for them and there are specialists in Sydney, Melbourne and Brisbane who know how to keep them running really well."

The majority that appear in the open market need work and are generally priced at less than \$2000. Getting one of these into useable condition can easily absorb as much money as an excellent 2000 or 2500TC will cost to buy and enjoy immediately.

Authentic PIs of either series can get expensive and a Mark 1 car was offered at more than \$20,000. Expect to pay \$12-15,000 for one in excellent – and reliable – condition.



Fast Facts

TRIUMPH 2000/2500/2.5 PI (1964-78)

NUMBER BUILT 120,645 (Mark 1), 195,311 (Mark 2)

BODY all-steel combined body/chassis, 4-door sedan and station wagon

ENGINE 2.0- or 2.5-litre, in-line six, OHV, twin sidedraft carburettors or fuel injection

POWER 98kW @ 5400rpm*

TORQUE 205Nm @ 2000rpm*

SUSPENSION independent with coil springs, Macpherson struts, lower control arms, anti-roll bar on 2500S (f); independent, trailing arms, coil springs, telescopic shocks (r)

BRAKES disc/drum, power-assisted

TYRES 6.50x13 crossply, 165SR13, 175-185SR14 radial

PERFORMANCE 0-97km/h - 9.4sec; 0-400m - 17.1sec***

PRICE RANGE \$1000-\$15,000

CONTACT Triumph Sports Owners Association *http://www.tsoasa.com* *2.5 PI **2.5 PI manual